

TDS PRODUCT IMAGE SHEET >

VENTURA – NFBL - DOOR MECHANISM & CONTROLS

Image	TDS Part Number & Description	OE Part Numbers (FITTED TO VEHICLE MODEL)
	<p>B688 PIVOT BOLT (BOTTOM SUPPORT)</p>	<p>B688 <i>Ventura</i> ALL ORION/STRATA</p>
	<p>B689 DOORSHAFT BEARING BUSH</p>	<p>B689 <i>Ventura</i> ALL ORION/STRATA, NBFL RS</p>
	<p>B706 DOORSHAFT ROLLER BOLT</p>	<p>B706 <i>Ventura</i> ALL ORION/STRATA</p>
	<p>C199 HANDGRIP</p>	<p>C199 <i>Ventura</i> Bluebird Pneumatic Extended, Bluebird Pneumatic, Bluebird Electrical, NFBL PS</p>
	<p>C492 VIBRATION DAMPER 20x15</p>	<p>C492 <i>Ventura</i> ALL ORION/STRATA</p>

	<p>D273-002 NOSING DOOR SEAL 2200MM LH CUTOUT</p>	<p>D273-002 <i>Ventura</i> Bluebird Pneumatic Extended, Bluebird Pneumatic, Bluebird Electrical</p>
	<p>D331-022 SENSITIVE EDGE 1760</p> 	<p>D331-022 <i>Ventura</i> Bluebird Pneumatic</p>
	<p>D331-024 SENSITIVE EDGE 1800</p>	<p>D331-022 <i>Ventura</i> Bluebird Pneumatic <u>Extended</u></p>
	<p>D331-053 SENSITIVE EDGE 1820 W (1,2KOhm)</p>	<p>D331-053 <i>Ventura</i> MELLOR ORION ELECTRIC/MANUAL RELEASE</p>
	<p>D331-060 SENSITIVE EDGE 1800 W (1,2KOhm)</p>	<p>D331-060 <i>Ventura</i> Bluebird Electrical</p>
	<p>D760 DOORSHAFT ROLLER SPACER</p>	<p>D760 <i>Ventura</i> ALL ORION/STRATA</p>

	<p>G952-001 PORTAL SEAL RS L=2200</p>	<p>G952-001 <i>Ventura</i> ALL ORION/STRATA</p>
	<p>H750 DOORSHAFT GUIDE ROLLER</p>	<p>H750 <i>Ventura</i> ALL ORION/STRATA</p>
	<p>J714 LOCK ASSY 1048-U14</p>	<p>J714 <i>Ventura</i> ALL ORION/STRATA</p>
	<p>J716 LOCK CYLINDER (KEY EK333)</p>	<p>J716 <i>Ventura</i> ALL ORION/STRATA</p>
	<p>K962-002 NOSING DOOR SEAL 2200MM LH CUTOUT GEN3 # APR17 > REPLACING WITH VA4802</p>	<p>K962-002 <i>Ventura</i> MELLOR ORION ELECTRIC/MANUAL RELEASE</p>
	<p>M106 BOTTOM SUPPORT RS LH ASSY # PIVOT BOLT = B688</p>	<p>M106 <i>Ventura</i> ALL ORION/STRATA</p>

	<p>M478 PORTAL STRIP RS 1100 (SECURES G952-001)</p>	<p>M478 <i>Ventura</i> ALL ORION/STRATA</p>
	<p>VA4644 HAND GRIP</p>	<p>VA4644 <i>Ventura</i> MELLOR ORION ELECTRIC/MANUAL RELEASE</p>
	<p>VA4802-002 NOSING DOOR SEAL 2200MM LH CUTOUT GEN4 # APR17 > REPLACED K962-002</p>	<p>VA4802-002 <i>Ventura</i> MELLOR ORION ELECTRIC/MANUAL RELEASE</p>
	<p>VA5484 > VB1319 EMERGENCY HANDLE INTERIOR # HANDLE GRIP = VA7984 (REPLACED BY VB1319 – JUN18)</p>	<p>VA5484 <i>Ventura</i> (MELLOR ORION RS ELEC)</p> 
	<p>VA5486 > VB3055 EMERGENCY HANDLE EXTERIOR WITH LOCK # LOCK CYLINDER = J716 # HANDLE GRIP = VA7984 # MICROSWITCH = VA6134 (REPLACED BY VB3055 – JUN18)</p>	<p>VA5486 <i>Ventura</i> (MELLOR ORION RS ELEC)</p> 
	<p>VA6134 EMERGENCY HANDLE MICROSWITCH</p>	<p>VA6134 <i>Ventura</i> (MELLOR ORION RS ELEC)</p>