


TDS PRODUCT IMAGE SHEET >

**VENTURA – NFBL - DOOR MECHANISM & CONTROLS**

Image	TDS Part Number & Description	OE Part Numbers (FITTED TO VEHICLE MODEL)
	<p><b>B688</b> PIVOT BOLT (BOTTOM SUPPORT)</p>	<p><b>B688</b> <i>Ventura</i> ALL ORION/STRATA</p>
	<p><b>B689</b> DOORSHAFT BEARING BUSH</p>	<p><b>B689</b> <i>Ventura</i> ALL ORION/STRATA, NBFL RS</p>
	<p><b>B706</b> DOORSHAFT ROLLER BOLT</p>	<p><b>B706</b> <i>Ventura</i> ALL ORION/STRATA</p>
	<p><b>C199</b> HANDGRIP</p>	<p><b>C199</b> <i>Ventura</i> Bluebird Pneumatic Extended, Bluebird Pneumatic, Bluebird Electrical, NFBL PS</p>
	<p><b>C492</b> VIBRATION DAMPER 20x15</p>	<p><b>C492</b> <i>Ventura</i> ALL ORION/STRATA</p>

	<p><b>D273-002</b> NOSING DOOR SEAL 2200MM LH CUTOUT</p>	<p><b>D273-002</b> <i>Ventura</i> Bluebird Pneumatic Extended, Bluebird Pneumatic, Bluebird Electrical</p>
	<p><b>D331-022</b> SENSITIVE EDGE 1760</p> 	<p><b>D331-022</b> <i>Ventura</i> Bluebird Pneumatic</p>
	<p><b>D331-024</b> SENSITIVE EDGE 1800</p>	<p><b>D331-022</b> <i>Ventura</i> Bluebird Pneumatic <u>Extended</u></p>
	<p><b>D331-053</b> SENSITIVE EDGE 1820 W (1,2KOhm)</p>	<p><b>D331-053</b> <i>Ventura</i> MELLOR ORION ELECTRIC/MANUAL RELEASE</p>
	<p><b>D331-060</b> SENSITIVE EDGE 1800 W (1,2KOhm)</p>	<p><b>D331-060</b> <i>Ventura</i> Bluebird Electrical</p>
	<p><b>D760</b> DOORSHAFT ROLLER SPACER</p>	<p><b>D760</b> <i>Ventura</i> ALL ORION/STRATA</p>

	<p><b>G952-001</b> PORTAL SEAL RS L=2200</p>	<p><b>G952-001</b> <i>Ventura</i> ALL ORION/STRATA</p>
 <p>H750</p>	<p><b>H750</b> DOORSHAFT GUIDE ROLLER</p>	<p><b>H750</b> <i>Ventura</i> ALL ORION/STRATA</p>
	<p><b>J714</b> LOCK ASSY 1048-U14</p>	<p><b>J714</b> <i>Ventura</i> ALL ORION/STRATA</p>
	<p><b>J716</b> LOCK CYLINDER (KEY EK333)</p>	<p><b>J716</b> <i>Ventura</i> ALL ORION/STRATA</p>
	<p><b>K962-002</b> NOSING DOOR SEAL 2200MM LH CUTOUT GEN3 # APR17 &gt; REPLACING WITH VA4802</p>	<p><b>K962-002</b> <i>Ventura</i> MELLOR ORION ELECTRIC/MANUAL RELEASE</p>
	<p><b>M106</b> BOTTOM SUPPORT RS LH ASSY  # PIVOT BOLT = B688</p>	<p><b>M106</b> <i>Ventura</i> ALL ORION/STRATA</p>

	<p><b>M478</b> PORTAL STRIP RS 1100 (SECURES G952-001)</p>	<p><b>M478</b> <i>Ventura</i> ALL ORION/STRATA</p>
	<p><b>VA4644</b> HAND GRIP</p>	<p><b>VA4644</b> <i>Ventura</i> MELLOR ORION ELECTRIC/MANUAL RELEASE</p>
	<p><b>VA4802-002</b> NOSING DOOR SEAL 2200MM LH CUTOUT GEN4 # APR17 &gt; REPLACED K962-002</p>	<p><b>VA4802-002</b> <i>Ventura</i> MELLOR ORION ELECTRIC/MANUAL RELEASE</p>
	<p><b>VA5484 &gt; VB1319</b> EMERGENCY HANDLE INTERIOR  # HANDLE GRIP = VA7984 <b>(REPLACED BY VB1319 – JUN18)</b></p>	<p><b>VA5484</b> <i>Ventura</i> (MELLOR ORION RS ELEC)</p>
	<p><b>VA5486 &gt; VB3055</b> EMERGENCY HANDLE EXTERIOR WITH LOCK  # LOCK CYLINDER = J716 # HANDLE GRIP = VA7984 # MICROSWITCH = VA6134 <b>(REPLACED BY VB3055 – JUN18)</b></p>	<p><b>VA5486</b> <i>Ventura</i> (MELLOR ORION RS ELEC)</p>
	<p><b>VA6134</b> EMERGENCY HANDLE MICROSWITCH</p>	<p><b>VA6134</b> <i>Ventura</i> (MELLOR ORION RS ELEC)</p>