



TDS PRODUCT IMAGE SHEET – CATEGORY > CYLINDER/RAMS

| Image | TDS Part Number & Description | OE & Alternative Part References (WHERE FITTED) |
|---|--|--|
|  | <p>CYL001A Ø63 Bore x 85 Stroke PNEUMATIC CYLINDER (BOSCH) # SEE REPLACEMENT CYL001U-12</p> | <p>216993-64 Peters LIMITED REFURB STOCK ONLY</p> |
|  | <p>CYL001B Ø63Bore x 85 Stroke PNEUMATIC CYLINDER (FESTO)</p> | <p>218073 Peters LIMITED REFURB STOCK ONLY</p> |
|  | <p>CYL001-RK CYLINDER SEAL REPAIR KIT – OLD PDS Ø63 Bore</p> | <p>216366-RK Peters</p> |
|  | <p>CYL001U-12 PØ63 Bore x 85 Stroke UNIVERSAL PNEUMATIC CYLINDER (PETERS REPLACEMENT) # BRK012 AVAILABLE SEPERATELY # UNIVERSAL SEAL REPAIR KIT ONLY= CYL200U-RK</p> | <p>214443 Peters 216366 Peters 216993-64 Peters 217430-002 Peters</p> |
|  | <p>CYL003A Ø63 Bore x 156 Stroke PNEUMATIC CYLINDER (BOSCH)</p> | <p>216993-01 Peters</p> |

| | | |
|--|--|---|
|  | <p>CYL003-RK CYLINDER SEAL REPAIR KIT – Bosch Ø63x156</p> | <p>216993-03/04 Peters</p> |
|  | <p>CYL004-11 Ø63Bore x 85 Stroke UNIVERSAL PNEUMATIC CYLINDER (PETERS REPLACEMENT) # BRK011 AVAILABLE SEPERATELY ## TDS CYL REPAIR KIT ONLY= CYL200U-RK</p> | <p>216993-04 Peters (EAST LANCs OMNIDEKKA)</p> |
|  | <p>CYL005A CYLINDER SEAL REPAIR KIT – Bosch 216993-64 & 04 SILVER FOR Ø63 BORE</p> | <p>216993-85 Peters 216993-04R Peters</p> |
|  | <p>CYL007-DNC-KIT TDS Ø63 Bore x 100 Stroke PNEUMATIC CYLINDER ASSY # SEP13 > REPLACED BY CYL007U-11-KIT</p> | <p>CYL007-DNC-KIT TDS (EARLIER TDS DOOR OPTARE VEHICLES)</p> |
|  | <p>CYL008B REAR BRACKET FOR CYL007-DNC-KIT ONLY TDS Ø63 BORE CYLINDER</p> | <p>CYL008B TDS (EARLIER TDS DOOR OPTARE VEHICLES)</p> |
|  | <p>CYL007U-11 TDS Ø63 Bore x 100 Stroke PNEUMATIC BASE CYLINDER # SEP13 > REPLACED CYL007B+CYL008B ASSY 2018 > SEE CYL075U-11</p> | <p>CYL007-11 TDS (LATER TDS DOOR OPTARE VEHICLES)</p> |
|  | <p>CYL007U-11-KIT TDS Ø63 Bore x 100 Stroke PNEUMATIC CYLINDER ASSY # SEP13 > REPLACED CYL007-DNC-KIT 2018 > SEE CYL075U-11-KIT</p> | <p>CYL007-11-KIT TDS (LATER TDS DOOR OPTARE VEHICLES)</p> |

| | | |
|--|---|--|
|  | <p>CYL009A Ø16x25 MINI ISO CYLINDER</p> | <p>216993-76 <i>Peters</i></p> |
|  | <p>CYL010-RK-KIT Ø63 BORE CYLINDER REPAIR KIT – OLD DEANS PARKER</p> | <p>039039 <i>Deans</i></p> |
|  | <p>PNE029U-RK SEAL REPAIR KIT FOR INTERNAL FLOW CONTROL VALVE USED ON PARKER CYLINDERS</p>  | <p><i>Deans/Peters</i></p> |
|  | <p>CYL010U-11 Ø63 Bore x 125 Stroke UNIVERSAL PNEUMATIC CYLINDER (DEANS REPLACEMENT) # BRK011 AVAILABLE SEPERATELY TDS CYL REPAIR KIT ONLY= CYL200U-RK</p> | <p>031130 <i>Deans</i> 046101 <i>Deans</i></p> |
|  | <p>BRK011-ADJ REAR BRACKET FOR Ø63 BORE TDS CYL010U FOR OLDER DESIGN DEANS 046101</p> | <p>BRK011-ADJ <i>TDS</i></p> |
|  | <p>BRK046-ASY = (V.5)Ø12 Rubber Bush for Ø50 Cyl + M8 Fixings</p> | |
|  | <p>CYL011U Ø63Bore x 75 Stroke UNIVERSAL PNEUMATIC CYLINDER (PETERS REPLACEMENT) # UNIVERSAL SEAL REPAIR KIT ONLY= CYL200U-RK</p> | <p>214442 <i>Peters</i></p> |



| | | |
|--|--|--|
|  | <p>CYL011U-12 Ø63Bore x 75 Stroke UNIVERSAL PNEUMATIC CYLINDER (PETERS REPLACEMENT) # BRK012 AVAILABLE SEPERATELY # UNIVERSAL SEAL REPAIR KIT ONLY= CYL200U-RK</p> | <p>217430-001 Peters</p> |
|  | <p>CYL013U Ø63Bore x 125 Stroke UNIVERSAL PNEUMATIC CYLINDER (PETERS REPLACEMENT) # UNIVERSAL SEAL REPAIR KIT ONLY= CYL200U-RK</p> | <p>214444 Peters</p> |
|  | <p>CYL014-RK-KIT CYLINDER SEAL KIT</p> | <p>46097 Deans</p> |
|  | <p>CYL021U-11 Ø63Bore x 76 Stroke UNIVERSAL PNEUMATIC CYLINDER (DEANS REPLACEMENT) # BRK011 AVAILABLE SEPERATELY # TDS CYL REPAIR KIT ONLY= CYL200U-RK</p> | <p>C23267 Deans 024208 Deans 031129 Deans 046098 Deans</p> |
|  | <p>CYL021U-14 Ø63Bore x 76 Stroke UNIVERSAL PNEUMATIC CYLINDER (DEANS REPLACEMENT) # BRK014 AVAILABLE SEPERATELY # TDS CYL REPAIR KIT ONLY= CYL200U-RK</p> | <p>D18541 Deans 018541</p> |
|  | <p>CYL022U-11 Ø63Bore x 80 Stroke RP=345 UNIVERSAL PNEUMATIC CYLINDER (OVERTON REPLACEMENT) # BRK011 AVAILABLE SEPERATELY # TDS CYL REPAIR KIT ONLY= CYL200U-RK</p> | <p>KNSC 063 058 080 Overton</p> |
|  | <p>CYL024U-11 Ø63Bore x 100 Stroke RP=365 UNIVERSAL PNEUMATIC CYLINDER (OVERTON REPLACEMENT) # BRK011 AVAILABLE SEPERATELY # TDS CYL REPAIR KIT ONLY= CYL202U-RK</p> | <p>Overton KNSC 063 054 0100 KNSC 063 120 0100 KNSC 063 084 0100 KNSC 063 058 0100 KNSC 063 058 0114</p> |

| | | |
|---|--|--|
| | | |
|  | <p>CYL026U Ø63Bore x 156 Stroke UNIVERSAL PNEUMATIC CYLINDER (PETERS REPLACEMENT) # TDS CYL REPAIR KIT ONLY= CYL202U-RK</p> | <p>215011 <i>Peters</i> 215046 <i>Peters</i></p> |
|  | <p>CYL026U-12 Ø63Bore x 156 Stroke UNIVERSAL PNEUMATIC CYLINDER (PETERS REPLACEMENT) # TDS CYL REPAIR KIT ONLY= CYL202U-RK</p> | <p>216367 <i>Peters</i></p> |
|  | <p>CYL027U Ø63Bore x 125 Stroke UNIVERSAL PNEUMATIC CYLINDER (PETERS REPLACEMENT) # TDS CYL REPAIR KIT ONLY= CYL202U-RK</p> | <p>214853 <i>Peters</i></p> |
|  | <p>CYL028U-KIT Ø50 Bore x 90 Stroke UNIVERSAL PNEUMATIC CYLINDER (DEANS REPLACEMENT) SUPPLIED WITH SENS MOUNT CLIPS + M14x1.5 NUTS # TDS CYL REPAIR KIT ONLY= CYL201U-RK</p> | <p>0101517 <i>Deans</i> <i>BELT DRIVE VERSION</i> H108167 <i>Deans</i></p> |
|  | <p>CYL029U-KIT Ø50 Bore x 140 Stroke UNIVERSAL PNEUMATIC CYLINDER (DEANS REPLACEMENT) SUPPLIED WITH SENS MOUNT CLIPS # TDS CYL REPAIR KIT ONLY= CYL201U-RK</p> | <p>0101538 <i>Deans</i> H108271 <i>Deans</i></p> |
|  | <p>CYL201U-RK Ø50 bore UNIVERSAL CYLINDER SEAL KIT (for TDS CYL028U & CYL029U)</p> | <p>CYL201U-RK <i>TDS</i></p> |

| | | |
|---|---|---|
|  | <p>CYL030U-11 Ø63 Bore x 76 Stroke PNEUMATIC CYLINDER/BRKT # TDS CYL REPAIR KIT ONLY= CYL202U-RK</p> | <p>CYL030-11 TDS (DENNIS EAGLE DUSTCART)</p> |
|  | <p>CYL034U-11 Ø63 BORE x 80 STROKE RP365 UNIVERSAL PNEUMATIC CYLINDER (OVERTON REPLACEMENT) # TDS CYL REPAIR KIT ONLY= CYL202U-RK</p> | <p>KNSC 063 056 080 Overton</p> |
|  | <p>CYL035U-11-KIT Ø63 Bore x 76 Stroke TDS PNEUMATIC CYLINDER ASSY</p> | <p>CYL035-11-KIT TDS (OPTARE SOLO SA EXPORT EXIT DR)</p> |
|  | <p>CYL037U-11 Ø63 BORE x 150 STROKE UNIVERSAL PNEUMATIC CYLINDER (DEANS REPLACEMENT) # TDS CYL REPAIR KIT ONLY= CYL200U-RK</p> | <p>0101495 Deans</p> |
|  | <p>CYL041 Ø100 BORE BODE CYLINDER FOR REPAIR KIT SEE CYL041-RK (CYLINDER REPLACED BY CYL058 a masats cylinder 101102DO)</p> | <p>720-2002-301 Bode</p> |
|  | <p>CYL041-RK Ø100 BORE CYLINDER BODE OR MASATS REPAIR KIT</p> | <p>For use on Cylinders > 720-2002-301 Bode Masats</p> |

| | | |
|--|--|--|
|  | <p>CYL042-RK Ø50 BORE CYLINDER REPAIR KIT - (PARKER)</p> | <p>Repair Kit for > 0101517, H108167 <i>Deans</i> 0101538, H108271 <i>Deans</i></p> |
|  | <p>CYL045B Ø32 BORE x 80 STROKE CYLINDER COMPACT (PETERS PLUG SLIDER) # RODEND = BRG085</p> | <p>218073-010 <i>Peters</i> EAST LANCS DD</p> |
|  | <p>CYL046 Ø40 BORE x 115 STROKE ISO CYLINDER (DEANS PLUG SLIDER)</p> | <p>0100316 <i>Deans</i> ADL E200</p> |
|  | <p>CYL050-100-01 12V x 100 EDRIIVE CYLINDER ASSY (INCL RODEND/PULLEY/PLATE)</p> | <p>CYL050-100-01 <i>TDS</i> TREKA BUS 16</p> |
|  | <p>CYL053-01 Ø50 BORE x 140 STROKE WABCO U-BOLT CYLINDER</p> | <p>422-812-0000 <i>Wabco</i> CITARO</p> |
|  | <p>CYL053-01RK Ø50 BORE REPAIR KIT WABCO CYLINDER</p> | <p>422-812-0002 <i>Wabco</i> CITARO</p> |
|  | <p>CYL058 Ø100 BORE VERTICAL CYLINDER MASATS (REPLACES CYL041U)</p> <p>CYLINDER SEAL REPAIR KIT CYL058-RK</p> | <p>101102D0 <i>Masats</i></p> |

| | | |
|--|---|----------------------------------|
|  <p>IMAGE TO FOLLOW</p> | <p>CYL058-RK CYLINDER SEAL REPAIR KIT FOR MASATS CYLINDER 101102DO *USE CYL041-RK*</p> | <p>1111DOD Masats</p> |
|  | <p>CYL059 Ø60 BORE x 140 STROKE WABCO U-BOLT CYLINDER</p> | <p>422 808 1060 Wabco</p> |
|  | <p>CYL065 PNEMATIC CYLINDER FOR LOCK SYSTEM</p> | <p>120016CO Masats</p> |
|  | <p>CYL068 NIGHT LOCK CYLINDER</p> | <p>130022CO Masats</p> |
|  | <p>CYL069 CYLINDER Ø80 BORE x 142 STROKE</p> | <p>180142HO Masats</p> |
|  | <p>CYL069-RK SEAL REPAIR KIT FOR CYLINDER 180142HO</p> | <p>1009700C Masats</p> |
|  | <p>CYL070-RK REPAIR KIT - MASATS LOCKING CYL 32BORE</p> | <p>1003620A Masats</p> |

| | | |
|---|---|--|
|  | <p>CYL075U-11 Ø63 Bore x 100 Stroke TDS PNEUMATIC BASE CYLINDER # MAR18 > REPLACED CYL007U-11 # TDS CYL REPAIR KIT ONLY= CYL202U-RK</p> | <p>CYL075U-11 TDS (LATER TDS DOOR OPTARE VEHICLES)</p> |
|  | <p>CYL075U-11-KIT Ø63 Bore x 100 Stroke TDS PNEUMATIC CYLINDER ASSY # MAR18 > REPLACED CYL007U-11-KIT # TDS CYL REPAIR KIT ONLY= CYL202U-RK</p> | <p>CYL075U-11-KIT TDS (LATER TDS DOOR OPTARE VEHICLES)</p> |
|  | <p>CYL079 MASATS CYLINDER 120016A0</p> | <p>120016A0 Masats</p> |
|  | <p>CYL079-RK Ø125 BORE RACK & PINION CYLINDER REPAIR KIT for Masats Cylinders >102147A0</p> | <p>1009202A Masats</p>  |
|  | <p>CYL080-RK Ø100 BORE RACK & PINION CYLINDER REPAIR KIT for BODE 720-3036-101 & 720-3036- 201 MASATS 101154CO</p> | <p>1009107B Masats</p>  |
|  | <p>CYL200U-RK Ø63 TDS UNIVERSAL CYLINDER SEAL KIT (ONLY FOR MODELS: CYL004U, CYL010U, CYL021U, CYL022U CYL033U, CYL037U, CYL049U)</p> | <p>CYL200U-RK TDS</p> |

| | | |
|--|---|---|
|  | <p>CYL201U-RK Ø50 TDS UNIVERSAL CYLINDER SEAL KIT</p> <p>(ONLY FOR MODELS: CYL028U, CYL029U)</p> | <p>CYL201U-RK <i>TDS</i></p> |
|  | <p>CYL202U-RK Ø63 TDS UNIVERSAL CYLINDER SEAL KIT</p> <p>(ONLY FOR MODELS: CYL001U, CYL011U, CYL013U, CYL024U, CYL026U, CYL027U, CYL030U, CYL034U, CYL038U, CYL039U, CYL054U, CYL057U, CYL071U)</p> | <p>CYL202U-RK <i>TDS</i></p> |
|  <p>IMAGE TO FOLLOW</p> | <p>CYL203U-RK Ø63 TDS UNIVERSAL CYLINDER SEAL KIT</p> <p>(ONLY FOR MODELS: CYL007U, CYL035U, CYL048U)</p> | <p>CYL203U-RK <i>TDS</i></p> |
|  | <p>CYL240-450 Ø40 BORE x 450 STROKE RODLESS CYLINDER (PETERS PLUG SLIDER)</p> | <p>218073-011 <i>Peters</i> EAST LANCS DD</p> |
|  | <p>CYL240-535-RK Ø40 BORE x 535 STROKE RODLESS CYLINDER REFURBISHED UNIT (ORIGINAL DIRTY UNIT NEEDED) # SEAL REPAIR KIT = CYL240-RK</p> | <p>0101621 <i>Deans</i> ADL E200 SD</p> |
|  | <p>CYL240-615-RK Ø40 BORE x 615 STROKE RODLESS CYLINDER REFURBISHED UNIT (ORIGINAL DIRTY UNIT NEEDED) # SEAL REPAIR KIT = CYL240-RK</p> | <p>0108290 <i>Deans</i></p> |
|  | <p>CYL240-RK CYLINDER SEAL/BAND FULL REPAIR KIT - PKR RODLESS 40BORE</p> | <p>Repair Kits for > 0101621 <i>Deans</i> 0108290 <i>Deans</i></p> |

| | | |
|--|--|--|
|  | <p>CYL400-001 12V GEAR BOX-ASSY 700232-T2</p> | <p>B700232 <i>BCE</i></p> |
|  | <p>KIT013 ACTUATOR REAR FIXING KIT A</p> | <p>KIT013 <i>TDS</i></p> |
|  | <p>A723 FORK JOINT 16x32 M16 IG CYLINDERS</p> | <p>A723 <i>Ventura</i> ALL IG CYLINDERS</p> |
|  | <p>A725 SPRING PIN (USED ON FORK A723)</p> | <p>A725 <i>Ventura</i> ALL IG CYLINDERS</p> |
|  | <p>C290 FORK JOINT</p> | <p>C290 <i>Ventura</i></p> |
|  | <p>C434 Ø32x730 BASE PS RODLESS CYLINDER (used for D622/F168)</p> | <p>C434 <i>Ventura</i></p> |
|  | <p>D436 Ø63x160 ASSY CYLINDER (IG) # SEAL REPAIR KIT = VA2982</p> | <p>D436 <i>Ventura</i></p> |








| | | |
|--|--|---|
| | D622 Ø32x1170 RODLESS CYLINDER ASSY (PS) | D622 <i>Ventura</i> PLAXTON PRESIDENT DD PS |
| | E321 Ø32x100 CYLINDER ISO-VDMA | E321 <i>Ventura</i> ADLE200EV, Polish Scania Omnicity DD IG3 (OLD) |
| | E328 Ø32x895 BASE RODLESS CYLINDER (E820/VA3604) | E328 <i>Ventura</i> WRIGHTBUS ECLIPSE SD PS + GEMINI DD PS (LATER) + STREETLITE SD PS + STREETCAR PS, NBFL RS OPTARE TEMPO SD PS |
| | E820 Ø32x895 ASSY RODLESS CYLINDER (PS) TDS REFURB SERVICE = E820-RK # BASE CYLINDER = E328 # SEAL REPAIR KIT = K586 | E820 <i>Ventura</i> WRIGHTBUS ECLIPSE SD PS + GEMINI DD PS (LATER) + STREETLITE SD PS + STREETCAR PS, OPTARE TEMPO SD PS |
| | F168 Ø32x730 ASSY RODLESS CYLINDER (PS) TDS REFURB SERVICE = F168-RK # SEAL REPAIR KIT = K587 | F168 <i>Ventura</i> WRIGHTBUS GEMINI DD PS (OLDER) |
| | F922 Ø32x795 ASSY RODLESS CYLINDER (PS) TDS REFURB SERVICE = F922-RK # SEAL REPAIR KIT = K585 | F922 <i>Ventura</i> POLISH SCANIA OMNICITY DD PS |
| | G920 RODLESS CYLINDER ASSY | G920 <i>Ventura</i> |
| | H836-RK Ø50 BORE SEAL REPAIR KIT FOR FESTO CYLINDERS > H774, H836, H837 | H836-RK <i>Ventura</i> ALL IG DOORS PRE 2011 |


| | | |
|--|---|---|
|  | <p>H836 Ø50x125 IG DOOR CYLINDER LH ASSY # NEW ASSY P/N = U345 # FESTO SEAL REPAIR KIT = H836-RK</p> | <p>H836 Ventura BASE CYL REPLACED BY P540 SEP11 > WRIGHTBUS ECLIPSE SD IG3 + GEMINI DD IG3, ADL E200 SD IG3 + E300 SD IG3 + E400 DD IG3, EAST LANCSD SD IG3 + OLYMPUS DD IG3, MCV SD 112/124RLE IG4</p> |
|  | <p>H837 Ø50x125 IG DOOR CYLINDER RH ASSY # NEW ASSY P/N = U344 # FESTO SEAL REPAIR KIT = H836-RK</p> | <p>H837 Ventura BASE CYL REPLACED BY P540 SEP11 > WRIGHTBUS ECLIPSE SD IG3 + GEMINI DD IG3, ADL E200 SD IG3 + E300 SD IG3 + E400 DD IG3, EAST LANCSD SD IG3 + OLYMPUS DD IG3, MCV SD 112/124RLE IG4</p> |
|  | <p>H840 Ø63x250 DOOR CYLINDER ASSY (IG3)</p> | <p>H840 Ventura</p> |
|  | <p>H895 Ø25x25 MINI CYLINDER ESN-25-25-P (5102)</p> | <p>H895 Ventura</p> |
|  | <p>I027 Ø50x125 CUSH EXTEN DOOR CYLINDER ASSY (IGP) # REPLACED BY P540 # SEAL REPAIR KIT = H836-RK</p> | <p>I027 Ventura POLISH SCANIA OMNACITY DD IG3 (LATER)</p> |
|  | <p>I486 Ø32x795 RODLESS CYLINDER ASSY (PSP) TDS REFURB SERVICE = I486-RK # SEAL REPAIR KIT = K585</p> | <p>I486 Ventura ADL E200 SD PS + E400 DD PS, EAST LANCSD SD PS + OLYMPUS DD PS, OPTARE VERSA SD PS, MCV EVOLUTION SD PS</p> |

| | | |
|--|--|--|
|  | <p>I662 MINI CYLINDER R1012-0025 RB</p> | <p>I662 <i>Ventura</i> POLISH SCANIA OMNICITY DD PS</p> |
|  | <p>K585, K586, K587 REPAIR KIT – VS PKR RODLESS CYLINDERS Ø32x795, Ø32x895, Ø32x730 I486/F922, E820, F168</p> | <p>K585, K586, K587 <i>Ventura</i></p> |
|  | <p>L269 Ø32x1100 DGC RODLESS CYLINDER # BASE CYLINDER OF N013 ASSY</p> | <p>L269 <i>Ventura</i> BLUEBIRD ORION RS PNEU</p> |
|  | <p>M001 Ø32x895 RODLESS CYLINDER LH ASSY</p> | <p>M001 <i>Ventura</i></p> |
|  | <p>M006 Ø63x125 DOOR CYLINDER LH ASSY (IG) with 1 x Reed switches # SEAL REPAIR KIT = M006-RK</p> | <p>M006 <i>Ventura</i> TEMSA SD IG4</p> |
|  | <p>M006-RK CYLINDER WEAR PART KIT</p> | <p>M006-RK <i>Ventura</i> TEMSA SD IG4</p> |
|  | <p>M007 Ø63x125 DOOR CYLINDER RH ASSY (IG) with 2 x Reed switches # SEAL REPAIR KIT = M006-RK</p> | <p>M007 <i>Ventura</i> TEMSA SD IG4</p> |

| | | |
|--|---|---|
|  | <p>N013 Ø32x1100 RODLESS CYLINDER L # BASE CYLINDER = L269 TDS REFURB SERVICE = N013-RK</p> | <p>N013 <i>Ventura</i> BLUEBIRD ORION RS PNEU EARLY MODELS</p> |
|  | <p>N985 Ø63x125 CYLINDER ISO 6431</p> | <p>N985 <i>Ventura</i> WRIGHTBUS NBFL DD IG4 PLAT</p> |
|  | <p>O578 Ø32 x 815 CYLINDER RODLESS SUB TDS REFURB SERVICE = O578-RK</p> | <p>O578 <i>Ventura</i> WRIGHTBUS NBFL DD PS</p> |
|  | <p>P536 Ø50x125 CYLINDER WITH EXT. PISTON</p> | <p>P536 <i>Ventura</i></p> |
|  | <p>P540 Ø50x125 DOOR CYLINDER (IGP) – NO REED SWITCHES REPLACES H836+7 BASE CYLINDER SEAL REPAIR KIT = P540-RK # PROXIMITY REED SWITCH = P539 # NOV17 – BEING REPLACED BY VB2290</p> | <p>P540 <i>Ventura</i> ALL ADL, WRIGHTBUS, MCV IG4</p> |
|  | <p>P540-RK CYLINDER SERIES 62-50 SEAL REPAIR KIT (P540, Q097, U343)</p> | <p>P540-RK <i>Ventura</i> VA2981 <i>Ventura</i></p> |
|  | <p>Q097 (E421) Ø50 x 160 DOOR CYLINDER ASSY (IGP) # SEAL REPAIR KIT = P540-RK</p> | <p>Q097 <i>Ventura</i> POLISH SCANIA OMNICITY DD IG3 (OLD)</p> |

| | | |
|---|---|---|
|  | <p>Q632 Elec Actuator 32x1065</p> | <p>Q632 <i>Ventura</i></p> |
|  | <p>R643 Ø32-RS1100 LH CYLINDER # BASE CYLINDER = Q342 TDS REFURB SERVICE = R643-RK</p> | <p>R643 <i>Ventura</i> BLUEBIRD ORION RS PNEU LATER MODELS</p> |
|  | <p>S234 Ø63 x 125 CYLINDER ASSY WITH EXT PISTON # SEAL REPAIR KIT = VA2982 APR18 > REPLACED BY VB2458</p> | <p>S234 <i>Ventura</i> WRIGHTBUS NBFL DD IG4 PLAT</p> |
|  | <p>S882 CYLINDER 27M2A032A0105</p> | <p>S882 <i>Ventura</i> WRIGHTBUS PS2</p> |
|  <p>22 873 ±0.04 (Out 1356 In 753)</p> | <p>S957 Ø25x 604 STROKE PS2 CYLINDER</p> | <p>S957 <i>Ventura</i></p> |
|  | <p>U343 Ø63 x 125 CYLINDER ASSY WITH EXT PISTON (P540 + 3xP539) # SEAL REPAIR KIT = P540-RK # PROXIMITY REED SWITCH = P539</p> | <p>U343 <i>Ventura</i></p> |

| | | |
|--|---|--|
|  | <p>VA1111 SPRING PIN</p> | <p>VA1111 <i>Ventura</i></p> |
|  | <p>VA1280 PS2 CYLINDER ASSY 1200 625 STROKE</p> | <p>VA1280 <i>Ventura</i> ADL E200 MMC</p> |
|  | <p>VA1283 PS2 CYLINDER ASSY 1350 700 STROKE</p> | <p>VA1283 <i>Ventura</i> MCV DD EVOSSETI PS2</p> |
|  <p>PIC TO FOLLOW</p> | <p>VA2982 CYLINDER SERIES 62-63 SEAL REPAIR KIT (Q089, D436, Q088, R668, S234)</p> | <p>VA2981 <i>Ventura</i></p> |
|  | <p>VA3604 Ø32 x 895 RODLESS CYLINDER ASSY # BASE CYLINDER = E328</p> | <p>VA3604 <i>Ventura</i> WRIGHTBUS NBFL RS PLAT</p> |
|  | <p>VA8946 PS2 CYLINDER ASSY 1270</p> | <p>VA8946 <i>Ventura</i></p> |
|  | <p>VB2458 Ø 63 x 125 CYLINDER ASSY WITH EXT PISTON APR18 > REPLACED S234 # PROXIMITY REED SWITCH = P539</p> | <p>VB2458 <i>Ventura</i> WRIGHTBUS NBFL DD IG4 PLAT</p> |

| | | |
|--|---|---|
|  | <p>VB2290 Ø50x125 CYLINDER FOR IG DOOR # NOV17 - REPLACES P540, H836+7 BASE CYLINDER SEAL REPAIR KIT = VB3592 # PROXIMITY REED SWITCH = P539</p> | <p>VB2290 <i>Ventura</i> ALL ADL, WRIGHTBUS, MCV IG4</p> |
|--|---|---|