

Overview Spare part boxes Wright

Version: 27 October 2015



United Kingdom

| System | System no. | Bus type | Doorleafs | Doorsub | Doorframe | Spare part box |
|--------|------------|----------------------|---------------------------|---------|-------------|----------------|
| IG4 | O889 | DD | P081 | N948 | N950 | VA3079-CL05 |
| | | | N947 / O892 / P082 / P573 | N949 | N951 | VA3082-CL05 |
| | P722 | SD | P667 / P928 | P669 | P671 | VA3087-CL05 |
| | | | P668 / P929 | P670 | P672 | VA3103-CL05 |
| L815 | Midi | L464 / S265 / VA2285 | L843 | L841 | VA3106-CL05 | |
| | | L465 / S266 / VA2286 | L844 | L842 | VA3110-CL05 | |
| n/a | KMB | M525 | M527 | M529 | U268-CL05 | |
| | | | M526 | M528 | M530 | VA0679-CL05 |
| IG3 | J636 | B7RLE Euro 4 | H526 / K016 | O916 | O915 | U273-CL05 |
| | | | H527 / K017 | O918 | O917 | VA3081-CL05 |
| | K054 | B7RLE Euro 4 SD | J763 / K077 | P740 | O915 | U273-CL05 |
| J641 | DD | H422 / I067 | J764 / K078 | P741 | O917 | VA3081-CL05 |
| | | | H454 / I077 | K865 | K859 | VA3084-CL05 |
| PS | K316 | Hybrid | I184 | n/a | n/a | VA3116 |
| | | | I185 | n/a | n/a | VA3115 |
| O851 | TFL | F013 | F014 | O847 | O846 | VA3101 |
| | | | | O849 | O848 | VA3094 |

Hongkong

| System | System no. | Bus type | Doorleafs | Doorsub | Doorframe | Spare part box |
|--------|------------|----------|-----------|---------|-----------|----------------|
| PS | M790 | KMB | M615 | M617 | M619 | VA3489 |
| | | | M616 | M618 | M620 | VA3491 |

NBFL

| System | System no. | Bus type | Doorleaf | Doorsub | Doorframe | Spare part box |
|--------|------------|----------|----------|---------|-----------|----------------|
| IG4 | N870 | NBFL | N867 | N868 | N869 | VA6322-CL05 |
| | | | N871 | N872 | N873 | VA6323-CL05 |
| N221 | NBFL | N242 | N991 | O732 | O733 | VA6324-CL05 |
| | | | | N990 | N989 | VA6325-CL05 |
| PS | O040 | NBFL | O036 | O037 | O038 | VA6326-CL05 |
| | | | O050 | O051 | O052 | VA6327-CL05 |
| RS | VA3449 | NBFL | VA3455 | VA3456 | VA3457 | VA6672 |