


VENTURA PS 1.0 – DOORSHAFT SERVICE KIT – P/N: KIT602



KIT COMPONENT PARTS
THIS IS A SINGLE DOORSHAFT/LEAF KIT, 2 REQUIRED PER DOUBLE DOOR SET

(2) H750 = GUIDE ROLLER ASSY Ø26x10 (bearing Ø22x6x10 bore)		(7) A732 = M6 A2 WASHER x 2	
(3) B706 = M10x40 FIXING BOLT		(8) B689 = DOORSHAFT BEARING BUSH x 2	
(5) C492 = VIBRATION DAMPER Ø20x15		(9) D803 = BOTTOM SUPPORT CATCH BLOCK	
(4) D760 = ROLLER SPACER BUSH Ø16 x 10 bore x 23.5 Lg		(9A) J405 = BOTTOM SUPPORT CATCH BLOCK	
(6) A760 = M6x16 FIXING BOLT		(10) C625-0.5ML = LOCTITE 243 TREADLOCKER Supplied in a 0.5ml Vial for retaining items 3 & 6	

ASSOCIATED CATCH PIN/WEDGE PLATES : REF ONLY NOT SUPPLIED IN KIT (AVAILABLE ON REQUEST)

D545 LH CATCH PIN ON PLATE 	D546 RH CATCH PIN ON PLATE 	E097 LH CATCH PIN ON PLATE 	E096 RH CATCH PIN ON PLATE
I275 LH CATCH WEDGE 	I276 RH CATCH WEDGE 	C924 CATCH PIN 	M801 CHECK IF REQ'D GUIDE ROLLER SECURING KIT SEE DOC SME013E

IF IN DOUBT ON PART SELECTION - PLEASE CONTACT US WITH DETAILS FROM THE DOOR LABEL ATTACHED TO TOP OF LEAF >

